

No. 2826

Facilities Available to Perform Field Loadable Software Upgrade

To: Universal FMS Operators using SCN 802.X or 902.X

Subject: Facilities Available to Perform Field Loadable Software Upgrade

Our records indicate that you are most likely operating FMS software 802.X or 902.X and you are affected by ALERT Service Bulletin 3307. If you have already complied with the Alert Service Bulletin or you are operating software other than 802.X or 902.X, then disregard this letter.

Your FMS should be upgraded to SCN 802.7 or 902.7, as applicable, as soon as practical. SCN 802.7/902.7 is described in detail in Service Bulletin 3314. SCN 802.7/902.7 is the recommended means of compliance with Alert SB 3307.

Universal is pleased to announce that there is no need to remove the units from your aircraft and ship them to a repair facility. This is a field loadable upgrade and is accomplished with the FMS installed in the aircraft. A kit has been created to allow specifically authorized facilities to perform this upgrade.

Contact any Universal Avionics Dealer for this upgrade. Some dealers will be able to perform this field loadable upgrade while others will remove the unit and send it in for upgrade.

Please visit <http://www.uasc.com/support/upgrade.aspx> for a list of facilities authorized by Universal Avionics to perform this field loadable software upgrade. Contact one of these facilities immediately to schedule the upgrade.